



# SIZING CHART

## Men's Armour

Measure	Position	S	M	L	XL	XXL
<b>A</b>	Chest circumference cm	76	80	84	88	92
<b>B</b>	Length cm	50	51.5	53	55.5	57
<b>C</b>	Hip circumference cm	70	74	78	82	86

